

# Handling & Storage

## Storing Palliside on site.

Palliside Product should be stored away from areas prone to excess dirt and debris. Cartons should be kept out of the exposed weather.

This is to protect the product from damage in case there is surplus material at the end of the job that you would like credited

## Carrying Weatherboards.




Packs of weatherboard should be lifted and not be dragged along the ground. A full pack weighs over 30kg.

Moving these packs is a 2 person lift.



## Surplus Materials at the end of the job.

Surplus product\* may be returned for credit providing that the following conditions are met:

1. The product to be returned is within a 60-day window from date of purchase
2. The product is in 100% resalable condition (Obvious question, would you be happy to receive it this way)?
3. Product and packaging is free of rips tears and construction site debris.
4. Weatherboard packs are to be stacked in the crate as they came (vertically as shown). Use a brace as necessary to hold packs in this position. 
5. An RMA form must be obtained by Dynex before the goods can be returned. A copy of the RMA must accompany the return. 
6. Transportation of product is to be arranged by the distributor and the costs of this transportation is to be met by the customer 
7. A restocking fee of 15% with a minimum \$25 charge is applicable for all Product that is surplus to requirement

\*Product made to order (such as custom lengths of weatherboard) cannot be returned for credit